

True RMS Clamp Meter Hand Held

- 1> AC Current : 0 to 999.9 A $\pm 2\%$
- 2> AC Voltage : 0 to 1000 V $\pm 1\%$ upto 600V and $\pm 1.5\%$ beyond 600V
- 3> Inrush current (integration time) : 100 millisecond
- 4> DC Current : 0 to 999.9 A $\pm 2\%$
- 5> DC Voltage : 0 to 1000 V $\pm 1\%$
- 6> Resistance : 0 to 4000 Ω $\pm 1.5\%$
- 7> Continuity : Less than or equal to 30 ohm
- 8> Frequency : 10 to 400 Hz $\pm 0.5\%$
- 9> Backlight Display : Provided
- 10> Operating temperature : 0 to (+) 50 deg C, 40 deg C at 75% RH
- 11> Type : Battery operated
- 12> Safety Rating : Category 3 600V IEC 61010-2-031
- 13> Jaw size (dia in closed state): 38 mm or more.