


Properties:-

Hardness :- Shore-D(70±5)

Ash content Maximum:-11%

for 4" NB IS3589 FBW thickness 6.25

Flange drilled as per BS-10 table-D

[illegible]