

Annexure –“A”

PR no / dtd **Supply of Ball Mill and Rod Mill head bolts**

| Sl. No | Material code | Material Description | Unit code | Stock in hand | Dues | Consumption rate | Item cat | Qty reqd. |
|--------|----------------|---|-----------|---------------|------|------------------|----------|-----------|
| 01 | 3.019.001.016 | HEX.BOLT M39x4.0x300-8.8 IS:1364 (p-1) – ISO4014- | | | | | | 30 |
| 02 | 3.019.001. 017 | Punched washer: A42 IS: 2016 | | | | | | 60 |
| 03 | 3.019.001. 018 | HEX.NUT M39x4.0 - 8 IS:1364 (P-3)- ISO4032 – | | | | | | 120 |
| 04 | 3.019.001. 019 | HEX.BOLT M39x4.0x240-8.8 IS:1364 (p-1) – ISO4014- | | | | | | 30 |
| 05 | 3.019.001. 020 | HEX.BOLT M20x2.5x100 – 8.8 IS: 1364 (P-1) – ISO 4014 | | | | | | 48 |
| 06 | 3.019.001. 021 | Punched washer: A22 IS:2016 | | | | | | 84 |
| 07 | 3.019.001. 022 | HEX.NUT M20x2.5-8 IS:1364 (P-3) – ISO 4032 | | | | | | 48 |
| 08 | 3.019.001. 026 | HEX.SCREW M33x3.5x240-8.8 IS:1364 (p-2) – ISO4017- | | | | | | 20 |
| 09 | 3.019.001. 027 | Punched washer: A36 IS: 2016 | | | | | | 96 |
| 10 | 3.019.001. 028 | HEX.NUT M33x3.5 - 8 IS: 1364 (P-3)- ISO4032 – | | | | | | 96 |
| 11 | 3.019.001. 029 | HEX.BOLT M33x3.5x180-8.8 IS: 1364 (p-1) – ISO4014- | | | | | | 24 |
| 12 | 3.019.001. 023 | HEX.SCREW M12x1.75x35-4.6 IS: 1363(p-2) – ISO4018 | | | | | | 50 |
| 13 | 3.019.001. 024 | Spring washer : B12 IS.3063 | | | | | | 50 |
| 14 | 3.019.001. 025 | Grub screw CM10x1.5x35 IS:6094-10.9 | | | | | | 50 |

1
Rajiv